



AU-H101A

**18G HDMI Repeater
w/ Audio Extraction**


Upgrade Instruction

AU-H101A 18G HDMI Repeater w/ Audio Extraction


1, Copy the update software “EPConsole” and firmware files to a PC.

2, Power the unit off, connect the FW port to PC via USB cable, it will be recognized as a COM port device on PC. Open the update software to select the COM port and baudrate set to 57600. Do not power the unit back on until step 5.

(Suggested to use win10, as win10 will install all driver automatically, but win7 or win8 maybe need to install the USB driver manually)



3, Click the “Start Console” and enable “Console input”.



AU-H101A 18G HDMI Repeater w/ Audio Extraction

4, Click “file” to select the firmware files, as below.



5, Reconnect the power of the unit to load the firmware file. Then click “Program MCU” button to start the firmware update, you will get the result after firmware update finish, as below shows.

